MOTION

The Bureau of Engineering (BOE) has conducted a field investigation assessing the condition and stability of a slope abutting Broadway near 3660 and 3830 North Broadway in the Lincoln Heights neighborhood. At this location, soil and debris from the slope have covered a portion of the sidewalk and the road itself. BOE's investigation also found that the dislodged soil has built up along a stairway at this site and displaced fencing along the stairway. Soil and debris have also covered part of the retaining wall along this street segment and the retaining wall is damaged and constructed of deteriorating wood.

This buildup of dirt and debris is a hazard to pedestrians and drivers and it is imperative the City take action to quickly return this street segment to a proper condition. BOE has referred this site to its Hillside Slope Stability Program to evaluate permanent repairs. As a temporary fix, BOE is recommending that the soil and debris on the sidewalk, stairway, and road be removed and the fencing along the stairwell be repaired.

I THEREFORE MOVE that the Bureau of Engineering and Bureau of Street Services, with the assistance of the Department of Water and Power, be instructed to report back with a plan and timeline for restoring the segment of Broadway near 3660 and 3830 North Broadway to a proper condition in a timely manner.

I FURTHER MOVE that the City Administrative Officer, with the assistance of the Bureau of Engineering and Bureau of Street Services, be instructed to identify funding to restore this segment of Broadway.

PRESENTED BY:

KEVIN DE LEÓN

Councilmember, 14th District

SECONDED BY:

majs

SEP 2 3 2022